



Please note: The 'V' indicated below is NOT a manufacturing fault. It is deliberate. This is where the two ends of the wool wrap come together and inserted into the gap. Without this, there would be a ridge where the join is and would effect the polishing!

