



Product Name: Nuvite C-49 'Supercleaner'

Part Number:

- 1 Gallon Concentrate – N215
- 5 Gallon Concentrate – N215A

Pack:

1 or 5 US Gallon containers.

Manufacturer: Nuvite Chemicals

Approvals:

- Douglas CSD #1
- Boeing D6-17487
- D6-1727
- Airbus NTO for safety to bare and clad 2024, 7075, 2524 aluminium, cadmium plated steel, mild steel, high-strength steel, plexi-glass, and paint.
- FAR 25.853 Burn Tested

HS Commodity Code: 3402.90.5030

Product Description.

Nuvites' C-49 'SuperCleaner' is the most versatile and effective cleaner available for cleaning fabrics, leather, carpet, plastics, laminates and even metals! In other words, for cleaning all types of surfaces generally found in commercial & private aviation, building or institutional interiors, automotive and marine interiors, or even home interiors! It's biodegradable, has a pleasant, clean smell and is safe for users and all your interior surfaces. It's extremely easy to use and is supplied in concentrated form, so dilution can be varied for a wide range of needs.

Core Benefits.

- Cleans plastics, fabrics, carpets, leather, vinyl, stainless steel, finished wood and even high gloss polyurethane finishes
- Safe and pleasant for users and the environment
- Will not damage paint, plastics, fabrics (including woollens), decorator fabrics, upholstery, finished leather or carpets
- Gentle, effective cleaning and leaves a pleasant fresh aroma
- Safe to plastics, rubber and all metals
- Completely biodegradable
- Non-flammable and non-corrosive to all metals
- Hard water stable, cold water efficient
- Supplied in convenient concentrate for dilution with tap water to fit any need

Directions for use.

Spot cleaning: Dilute Nuvite C-49 1:8 with water. Spray a cotton cloth to dampen cloth, then apply to soiled spots. Soak out as much soil as possible into a dry cotton cloth. If soil spot persists after soaking with towel, spray C-49 directly on spot and use soft brush to agitate up and down, then side to side. Re-apply dry cotton cloth to soak out agitated residue. Repeat as needed. Finally, lightly spray around general area of spot, and work surface with up and down then side-to-side action with a dry cotton cloth. Refer to MSDS for health & safety information. Contact Frasers Aerospace representatives for further information and assistance.

For broad areas: Dilute C-49 to 1:12. Clean soiled area with up/down, then side to side action with C-49 dampened cotton cloth. As surface becomes wet, switch to dry cloth. Refer to MSDS for health & safety information. Contact Frasers Aerospace representatives for further information and assistance.

For leather: after cleaning very soiled areas with C-49, replace oils and surface condition with Nuvite Leather Guard. Refer to MSDS for health & safety information. Contact Frasers Aerospace representatives for further information and assistance.

Safety & storage.

C-49 SuperCleaner is not environmentally restricted. Users should use standard safety precautions, such as wearing gloves and eye protection along with any other standard safety procedures. Refer to Material Safety Data Sheet for further information.